


ACTIVINSPIRE TIPS AND TRICKS

Calibrating Your Board

There are two ways to calibrate the board.

From Your Desktop

- Right click on the ActivManager from your taskbar at the bottom of the screen.
- Select **Calibrate**.
- Use the barrel of the pen and touch the center of the five crosses on the board.



From Your Board

- Hover your pen over the flame on the top left corner of the board.
- Select **Calibrate**.
- Use the barrel of the pen and touch the center of the five crosses on the board.